ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura
Street ID	**Street Name**	**Significant Landmark**
W0478, W0589, W0476	NA, 7th Crs	Maruthi farm
Segment No.	**Total Length (m)**	
7/C-W0478/S031546	209.72	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	24.30	77.596349	13.059784	77.596569	13.059742	Main Road	Dead End
2	24.55	77.596389	13.059980	77.596614	13.059959	Main Road	Dead End
3	160.87	77.596539	13.061093	77.596298	13.059661	Maruthi Farm Main Road	Dead end

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Package 03 Includes 1 works of Rs 85.00 Lakhs. 1) Improvements to drains roads in Maruthi farm in Amruthanagara A sector in ward no 07 Byatarayanapur	8500000	2019-20
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Tender	1.Removing and reseeting B.S Slab Drains.2.Construction of Solid block brick masonry.3.Providing and laying B.S Slab.4.Providing and laying Kerb Stones.5.Providing Rain water Harvesting(RWH)6.3rd Main Road, 5th cross, Maruti farm Main road, 1st 2nd and 3rd cross, 2nd main Road and 6th Cross als	007-19-000011
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/80/20-21	19/08/2020	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
11/01/2021	10/01/2024	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released
U.Ramesh		0.00
Phone No.	**E-Mail ID**	
7846844447		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Pushpalatha.N.D
Date of Inspection	**Remarks**	
11/01/2021		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0478, W0589, W0476

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.S.P.Ranganath	11/01/2021	10/02/2021	As proposed
SE	Vijay Kumar Haridas	11/01/2021	10/02/2021	Forwarded
EE	Mohandas.H.T	11/01/2021	10/02/2021	Verified
AEE	G.Srinivasa Murthy	11/01/2021	10/02/2021	Verified
AE	Pushpalatha.N.D	11/01/2021	10/02/2021	Mobile Verification Done
AE	Pushpalatha N.D	11/01/2021	10/02/2021	Forwarded

Assistant Executive Engineer
Kodigehalli Sub Division
Bruhat Bangalore Mahanagara Palike
Bangalore - 560 092

Pushpa L.Y.N.D
AE(W01)

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0478, W0589, W0476